



Government of Maharashtra
Office of the Executive Engineer
Public works Division, Ashti



Contact No.: -02442-2222474	E-mail- spbeed.ee@mahapwd.gov.in	Fax No.
Letter No/Road/753		Dated: 15.06.2026

Ref.: Principal, Anisha Global School, Ashti, Tal-Ashti, Dist-Beed
Letter Dated 01/06/2026

BUILDING SAFETY CERTIFICATE

1	Name of the School	Shri. Pimpaleshwar Mahadev Devasthan's Anisha Global School
2	Village, Town, District in which the School is Situated	Ashti, Tal-Ashti, Dist-Beed
3	Full Postal Address of School	Malmatta No. 1913, Sr. No. 472 & 473, Jamgaon Road, Ashti, Tal-Ashti, Dist- Beed
4	Name of the Occupier of School	Shri. Pimpaleshwar Mahadev Devasthan
5	Name of the Activity to be carried in the School	Education 1" to 10" standard
6	Number of Floors	Two Floors (Ground Floor + First Floor)

I certify that I have inspected the premeases to the Plans which have been approved by Grampanchayat, Ashti dated 31/03/2015 & examined & tested the various parts including the Foundations Structural Members, Walls etc. I am of the opinion that all the works of Engineering Constructions in the premises is structurally sound & that its stability and safety will not be endangered by its use as a School/part of a School for the Education or of the items mentioned in serial No. 5 as above for which the building is intended the Certificate is valid for five years.

I further certify that to the best of my knowledge the structural work is carried out as per prescribed applicable standards and codes, rules, regulations and stipulations, the material used workmanships and methodology employed for construction work are accepted standards and the work is complete render to fit for occupation for intended use.

This certificate is issued on the clear understanding that my overall responsibility for the safety and proper performance of structure ceases, the moment any addition or alteration damage to the structural frame is caused by accident or by tempering with the geometrical section of structural members for any purpose whatsoever or due to over loading of the structural, lack of maintenance or any act that is detrimental to the structural as a whole.


Executive Engineer
Public Works Division, Ashti.